



## Town of Atherton 6c

### **PARK & RECREATION COMMITTEE STAFF REPORT**

**TO: PARK AND RECREATION COMMITTEE**

**FROM: STEVE TYLER, PUBLIC WORKS SUPERINTENDENT**

**DATE: JULY 5, 2017**

**SUBJECT: PARK GOINGS ON JUNE 2017**

#### **REGULAR STAFF**

- Perform regular maintenance tasks;
  - Pick litter/trash.
  - Remove trash bags.
  - Blow and pick up tree leaves and debris.
  - Inspect and maintain restrooms.
  - Inspect and maintain tennis courts.
  - Inspect and maintain playgrounds.
  - Inspect and maintain Main House elevator.
  - Control undesirable weeds throughout property.
  - Cut back and remove tree brush and dead vegetation.
  - Apply seasonal fertilizers to turf and plants.
  - Inspect and maintain landscape irrigation.
  - Inspect and maintain landscape irrigation well and filter system.
  - Potable water usage is being monitored daily.
  - Water non-established trees throughout the park based on schedule.
  - Blow tennis courts 2 times per week and as required.
  
- Potable water leak got repaired by CALWATER at Watkins Ave on 06/08/17.
- Wire splicing got re-done at all 14 valves in the Event Garden area.
- Old flow sensor at HP Park main pump got replaced with new one, due to cut off wire.
- A 4" main line irrigation water leak at Event Garden got repaired on 06/12/17 by Frank & Grossman Co.
- A 4" main line irrigation water leak at HP Park by Main Pump got repaired on 06/17/17 by MCE Techs.
- Wood chip by Little League field, got spread all along and around the Tennis Court area.
- Pipe lines got flushed, five (5) 1 ½" automatic valves and all rotors got replaced at North Meadow turf.
- Little League field and building got all cleaned and improved for tournament events.
- Little League All-Star Tournament held at Homer Field June 24 – July 4.

- New and future planned projects;
  - Rebuilt U shape driveway between Main House and water fountain grass.
  - Electric Vehicle Charging Stations will be installed at Main House.
  - New ceiling rebuild in Art Center room at Main House.
  - New Bike Rack getting install along and between tennis court and little league area.



**Cal Water break at Atherton Channel caused a potable water shut down in the park for about 6 hours.**



LEFT – New flow sensor installed in system adjacent to new well..

BELOW – 4” main line leak inside new Event Garden.





TOP LEFT – Another 4”  
water line break next to  
water tank in Corp. Yard.



BOTTOM LEFT – New  
wood chips spread around  
rear of tennis courts.



Left – irrigation repairs

